



# ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਮੰਡਲ

(੯)

ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ (ਭ ਤੇ ਮ) ਸਾਖਾ ਲੁਧਿਆਣਾ।

Phone/Fax No. 0161-2420082

Email-ID :- eepdldnpwdpb@gmail.com

ਵੱਲ

ਪ੍ਰਿੰਸੀਪਲ

ਐਸ.ਐਸ.ਐਨ. ਕੋਨਵੈਂਟ ਸੀਨੀਅਰ ਸੈਕੰਡਰੀ ਸਕੂਲ,  
ਚਰਨ ਨਗਰ (ਪ੍ਰੇਮ ਵਿਹਾਰ ਟਿੱਬਾ ਰੋਡ), ਲੁਧਿਆਣਾ।

ਨੰ. ੪੫੦੩

ਮਿਤੀ: 22/11/25

ਵਿਸ਼ਾ:- Request to renewal our Building safety Certificate.

ਹਵਾਲਾ: ਆਪ ਦਾ ਪੱਤਰ ਨੰ.-4248/SSN/2024 ਮਿਤੀ 24/12/2024

ਉਪਰੋਕਤ ਵਿਸ਼ੇ ਤੇ ਹਵਾਲੇ ਦੇ ਸਬੰਧ ਵਿੱਚ ਆਪ ਨੂੰ ਲਿਖਿਆ ਜਾਂਦਾ ਹੈ ਕਿ ਐਸ.ਐਸ.ਐਨ. ਕੋਨਵੈਂਟ ਸੀਨੀਅਰ ਸੈਕੰਡਰੀ ਸਕੂਲ, ਚਰਨ ਨਗਰ (ਪ੍ਰੇਮ ਵਿਹਾਰ ਟਿੱਬਾ ਰੋਡ), ਲੁਧਿਆਣਾ ਦਾ ਨਿਰੀਖਣ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਉਪ ਮੰਡਲ ਨੰ. 3, ਲੁਧਿਆਣਾ ਵੱਲੋਂ ਕੀਤਾ ਗਿਆ ਅਤੇ ਉਨ੍ਹਾਂ ਦੀ ਰਿਪੋਰਟ ਮੁਤਾਬਕ ਸਕੂਲ ਦੀ ਬਿਲਡਿੰਗ ਮਿਤੀ 31/03/2028 ਤੱਕ ਸਹੀ ਜਾਪਦੀ ਹੈ। ਸਕੂਲ ਦੀ ਬਿਲਡਿੰਗ ਵਿੱਚ ਇਸ ਦਫਤਰ ਦੀ ਮੰਨਜ਼ੂਰੀ ਤੋਂ ਬਗੈਰ ਕੋਈ ਵੀ ਐਂਡੀਸ਼ਨਲ ਅਲਟਰੇਸ਼ਨ ਨਾ ਕੀਤੀ ਜਾਵੇ ਅਤੇ ਹਰ ਸਾਲ ਸਕੂਲ ਦਾ ਇੰਸਪੈਕਸ਼ਨ ਕਰਵਾਉਣ ਉਪਰੰਤ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਲੈਣਾ ਯਕੀਨੀ ਬਣਾਇਆ ਜਾਵੇ।

ਨੱਥੀ/ਸਰਟੀਫਿਕੇਟ

ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ  
ਪ੍ਰਾਂਤਕ ਮੰਡਲ, ਲੋ.ਨਿ.ਵਿ.,  
ਭ ਤੇ ਮ ਸਾਖਾ ਲੁਧਿਆਣਾ।

ਪਿੱਠ ਅੰਕਣ ਨੰ.

ਮਿਤੀ:


ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਉਪ ਮੰਡਲ ਨੰ. 3, ਲੁਧਿਆਣਾ ਨੂੰ ਉਨ੍ਹਾਂ ਦੇ ਪੱਤਰ ਨੰ. 763 ਮਿਤੀ 9/01/2025 ਦੇ ਹਵਾਲੇ ਵਿੱਚ ਸੂਚਨਾ ਅਤੇ ਅਗਲੀ ਲੋੜੀਂਦੀ ਕਾਰਵਾਈ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ।

ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ  
ਪ੍ਰਾਂਤਕ ਮੰਡਲ, ਲੋ.ਨਿ.ਵਿ.,  
ਭ ਤੇ ਮ ਸਾਖਾ ਲੁਧਿਆਣਾ।

Part - 1

Perfuma For The Safety School Building  
(To be filled by the Head of School / Institute)

1. Name of School S.S.N. CONVENT SR. SEC. SCHOOL
2. Location CHARAN NAGAR (PREM-VINAR) TIBBAROA
3. Plot Area 5295.16 SQ. YARD
4. Plinth Area 46230 30954 SQ. FT.
5. Number of Storey Gt. Two
6. Year of Construction of building 2003
7. Supervision of the qualified Engineer,  
The following details may be given:
  - a) Name of the Engineer HIRALAL ARCHITECTS
  - b) Address HIRALAL ARCHITECTS  
CIVIL LINES LUDHIANA
  - c) Set of Structure Drawing used in the  
construction if available AS P.C.N.
  - d) Name of the Architect HIRALAL ARCHITECTS
8. Whether the building has been constructed for the purpose of:
  - a) School (Yes/No) YES
  - b) Residential purpose and converted  
for use as a school (Yes/No) NO
9. Materials used for Roof:
  - a) R.C.C. slabs (Yes/No) NO
  - b) R.S. Joists and Battens (Yes/No) NO
  - c) Wooden Joists and Battens (Yes/No) NO
10. Materials used for walls:
  - a) Mud Mortar (Yes/No) NO
  - b) Cement Mortar (Yes/No) YES
  - c) Plaster (i) Lime Mortar (Yes/No) NO
  - (ii) Cement Mortar (Yes/No) YES
11. Flooring :
  - a) Conglomerate (Yes/No) YES
  - b) Terrazzo (Yes/No) NO
  - c) Brick Paving (Yes/No) NO
12. Detailed Drawing indicating dimensions  
of the rooms along with size and location  
of doors and windows SCHOOL MAP ATTACHED

  
Principal  
S.S.N Convent Senior Secondary School  
Ludhiana

Principal  
S.S.N Convent Senior Secondary School  
Ludhiana  
Signature with stamp of  
The Head of the School / Institute

Part -II


(To be filled by S.D.E of P.W.D B&R Department)


Building Safety Report

Name of School:- SSN CONVENT SR. SEC. SCHOOL, LUDHIANA

I have visited the above mentioned school building along with Sh. Raj kumar on dated 09/01/2025 and have visually inspected. It seems visually safe subject to the following observation & conditions.

- a. Parameters to check the stability and safety of building such as Architectural Drawings, Bearing capacity, Foundation details Structural Drawings, Technical Specifications, Test Reports of Material used Quality Control reports and Certificate from Engineer in charge for Construction are not available.
- b. In case of any addition, alternation of expansion and modification of this building are done; certificate may be re- obtained after completion from undersigned.
- c. In case the building is affected by flood or if there is settlement of walls/ foundation or sagging of roofs etc., immediate inspection of the undersigned be arranged to check the stability and safety of the building.
- d. A separate certificate regarding Fire Fighting should be obtained from the competent authority.
- e. A separate certificate regard Electrical Work should be obtained from the competent authority.
- f. The owner of the building/Management is fully responsible regarding safety of building from all angels in spite of this report.
- g. The covered area of the building is .....
- h. This report is not valid for legal purpose.
- i. As per government order no. 5/13/2018-3BR3/1294287/3 DATED 10-08-2018 for issue of building safety certificate Para 2.0 (a), this certificate as requested by school authority is issued for period of 04 Years up to 31/03/2028

  
Engineer

  
Sub-Divisional Engineer  
Provincial Division No. 3,  
P. W. D. B & R Br., Ludhiana.